



<u>FIGURE-Index N°</u>	<u>PART N°</u>	<u>DESCRIPTION</u>	<u>Models affected, remarks</u>
		CANOPY page 2/2 plexiglas assembled with screws or rivets	(? 1992)
142	- 54 95 13 37 000	Screw	all models
	- 55 95 13 37 000	Screw	" "
	- 56 -----	Screw (not procurable)	" "
	- 57 95 24 02 000	Nut.....	" "
	- 58 95 14 03 000	Screw	" "
	- 59 95 24 02 000	Nut.....	" "
	- 60 95 55 02 000	Screw	" "
	- 61 28 26 36 000	Washer.....	" "
	- 62 -----	(deleted)	
	- 63 28 26 21 000	Cover, latching assembly (installed on 180R only, from 1988).....	all (1979? 1988) 180R only, after 1988
	- 64 76 34 37 010	Cover (loud speaker)	all, except 180 R (1988?)
	- 65 75 36 10 510	Washer (on request).....	all (1988 ? 1993)
	- 66 28 26 30 140	Washer, cup	" " "
	- 67 28 26 30 030	Seal	" " "
	- 68 -----	Washer.....	" " "
	- 69 25 36 16 000	Lock handle (inner)	" " "
	- 70a 28 26 30 010	Safety lock.....	" " "
	- 70b 28 26 30 120	Spindle.....	" " "
	- 71 28 26 30 020	Lock handle (outer).....	" " "
	- 72 28 26 54 000	Guiding stud	
	- 73 95 62 01 030	Washer (on request).....	(used before 1988)
	- 74 95 24 12 000	Nut.....	assembly superseded by parts 17 thru 19, Fig 147 after 1988
	- 75 95 14 06 000	Screw	
	- 76 95 14 16 000	Screw	
	- 77 95 41 13 000	Screw	
	- 78 25 34 08 010	Handle, inside (cast aluminium)	After 1988
	- 79 25 34 08 005	Handle, outside (cast aluminium).....	From 1988 to 1992